Work Order ID 51761 September 03, 2009 8:55:43 AM												Page 1
Item ID: Revision ID: Item Name:	D2230-1 F Lug			Accept					Setup	Start Stop		
Start Date: 09/02/09 Start Qty: 4. Required Date: 09/16/09 Req'd Qty: 4. Reference: Return 2009 / RA109088					Cust Item ID: Customer:							
Approvals:	Process Plan:QC:				Date:				Run Star Stoj			
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr											
D2230	Rev I	F										2
QC Quality Control		QC5- Inspect part comp Memo Original B4	leteness to step on W/O	0.00 ondition.	already.			4				65.05.0
110 Packaging Packaging		Memo	tock Location: Sty	0.00				4		1	4/4	1/9

120

QC

Quality Control

Memo

Location:

QC21- Final Inspection - Work Order Release

From" Return 2009". LL to Adjust

0.00

09609/08 Ad NUC 09-09-08